



APP-011

Chemical












Application notes

Moisture in cement raw clay

The CHINO IM series is an on-line multi wavelength analyzer utilizing infrared absorption technology to measure percent water in clay. The standard moisture range of the unit is 0.0% to 15.0% with a 0.3% resolution or 0.0% to 30.0% with a 0.8% resolution. Moisture control on cement clay plays an important role in order to determine high quality in its final form.

Controlling moisture may also be necessary to prevent the clay from sticking to conveyers or hopper, eliminating frequent process break and clean up. Signal processing capabilities are built into the compact designed detector unit for easy installation and operation. A maximum of 99 calibration curves can be stored into the detector memory for numerous measurement applications. The detector can be used by itself or connected to a PC or DCS plant control system. Both analog (4 to 20mA DC) and digital (RS-485 or LAN Ethernet) outputs are provided. A remote setting display unit, which connects up to 9 detector units, can be used to set various detector functions and also displays measured values.



Products / Location	Parameter	Range
Clay	Moisture	5 to 15%
Clay	Moisture	5 to 30%

Recommended model / Item

* General moisture unit

Model: IRMA1100S Qty:1

* Air purge hood

Model: IR-WEA Qty:1

* Checking plate


Model: IR-WEB Qty:1

Installation

Typical installation is over a conveyer with air purged protection box in order to prevent dust from clogging the measuring light path. In some cases, the level of the product on a conveyer may be not leveled evenly. It is recommended to use a leveling board prior to the measuring point.

Absorption characteristic

Calibration curve



Moisture(water) has a unique infrared

absorption spectrum regions. Water

absorbs at wavelength of 1.43, 1.94,

110.0 100.0 90.0 80.0 70.0 60.0 50.0 40.0 30.0 200 0.500 1.000 1.500 2.000 0.000

Calibration curve is a correlation between moisture determined by customer's reference instrument and IR absorption measured by IRMA.

[Basic sample test for moisture]

- 1. Prepare samples with various moisture content
- 2. Show each sample to IRMA and record absorption level
- 3. As conducting step-2, determine moisture level with your reference instrument
- 4. Put all data points on a X/Y graph and see if there's a correlation Note: Reference instrument may vary depending on the method (by volume or weight).



and 3 micrometers.







Liquid cell type



Setting & Display unit

Contact

Plot No. PAP-A-235-240, South Central Road, TTC Industrial Area, MIDC Mahape, Navi-Mumbai 400 710

Telephone: 022-4129-3000, 022-4129-3099